

30 Parkhead Gardens, Edinburgh, EH11 4RR "the Property"/ "the House")

Chamber Reference: FTS/HPC/RP/24/5358

SCHEDULE OF PHOTOGRAPHS





3 Damaged handle to kitchen window.



5 Example of incomplete filler over reinforcement tape to recent plastering works.



7 Wash basin in Bathroom.



2 Oven.



4 Plastering and painting undertaken to walls in Kitchen.



6 Living Room skirting refixed.



8 General view of Bathroom.



9 Distribution board.







15 Entrance door – smoke testing.



10 Distribution board.



12 Defective cistern flush.



14 Entrance door – letterbox.



16 Bathroom – general view.



17 Minor water damage to bath panel.



18 Small void adjacent to wash basin.



19 Sealant to bath.



20 Defective plasterwork adjacent to rear door.



21 Stored white goods.



22 Rear garden.



23 Cooker hood canopy in Kitchen.



24 View of Kitchen panelled ceiling.



25 Trickle vent in closed position.



27 Psychometric data – elevated relative humidity noted.



29 Minor mould growth at void area in Kitchen.



31 Condensation test - surface temperature above dewpoint however surface humidity at 85.7%.



26 Low level of wall to appliance recess in Kitchen.



28 Condensation test in Kitchen – surface temperature above dewpoint however surface humidity at 87.3%.



30 Living Room – mould present to external wall.



32 Dry skirtings to Living Room.



33 Elevated reading at base of wall to Living Room external wall.



34 Elevated reading at base of wall to Living Room external wall.



35 Bedroom – mould contamination.



36 Condensation test in Bedroom - surface temperature above dewpoint however surface humidity at 90.7%.



37 Condensation test in Bedroom - surface temperature above dewpoint however surface humidity at 89.0%.



38 Psychometric data – high relative humidity.