



Property Address


12 Pladda Avenue  
Broomlands  
Irvine  
KA11 1DR

Case Reference

FTS HPC RP 23 4306



Schedule of Photographs taken during the  
inspection by tribunal members on 11  
September 2024



1.Living room door from Hall



2. Front external door from inside



3. Living Room Radiator



4. Kitchen worktop




5. Kitchen drawer next to sink



6. Kitchen base unit door next to cooker



7. Repaired double socket outlet in Kitchen



8. Decayed floor board in Kitchen



9. Cistern to WC in Bathroom



10. Staining above window in Bathroom



11. Meter reading in stained area above Bathroom window



12. Bathroom door from landing





13. Sliding wardrobe doors in Bedroom2



14. Fence to front of property



15. Gutter to front of property



16. Fascia to front of property



17. Rear elevation of property